



Testing. Advising. Assuring.

EWFA CERTIFICATE OF ASSESSMENT	CERTIFICATE No : SFC 27349-01C	Page 1 of 1
---------------------------------------	---------------------------------------	--------------------



Report Sponsor	Certificate Issue Date	Product Name
Dortek Ireland North Quay, Wicklow Town County Wicklow, Ireland	28/03/2013	Dortek G.R.P Hinged Double-leaf Doorset

Assessment Report Reference	Referenced Standard	Report Issue Date	Report Validity Date
EWFA 27349-01	AS 1530.4- 2005 & AS1905.1- 2005	28/03/2013	30/09/2017

Introduction
The elements of construction described below were assessed by this laboratory on behalf of the report sponsor in accordance with the stated test standard and achieved the results stated below. Refer to the referenced assessment report(s) or Regulatory Information Reports for a complete description of the assessed construction.

Assessed system description and performance						
Door Leaf	Maximum Leaf Size	Max. Number of Hinges	Support Construction	Door Frame	Vision Panel	FRL
Double	2440mm high 1225mm wide	5 hinges per each leaf	Masonry Wall 215mm thick	G.R.P frame	Uninsulated and Area < 65000mm ²	-/120/60
					Insulated Glazing	-/60/30
Refer to the referenced assessment report(s) or Regulatory Information Reports for a complete description of the assessed construction.						

Conditions/Validity
<ul style="list-style-type: none"> THIS CERTIFICATE IS PROVIDED FOR GENERAL INFORMATION ONLY AND DOES NOT COMPLY WITH THE REGULATORY REQUIREMENTS FOR EVIDENCE OF COMPLIANCE. Reference should be made to the relevant test report or regulatory information report to determine the applicability of the test result to a proposed installation. Full details of the constructions and justification for the conclusions given, along with the validity statements, are given in the assessment reports. The assessment report or short form assessment report does not provide an endorsement by Exova Warringtonfire Aus Pty Ltd of the performance of the actual products supplied. It is intended to provide a brief outline of the above referenced assessment reports and not to replace them. The conclusions in this certificate of assessment relate to the configurations as detailed, and should not be applied to any other configuration. The conclusions expressed in this document assess fire hazard, but it should be recognised that a single test method will not provide a full assessment of fire hazard under all conditions. Full copies of the assessment and relevant test reports may be obtained from the sponsor.

TESTING AUTHORITY	Exova Warringtonfire Aus Pty Ltd
Address	Suite 2002a, Level 20, 44 Market Street, Sydney NSW 2000, Australia
Phone / Fax	+61 (0)2 8270 7600 / +61 (0)2 9299 6076
ABN	81 050 241 524
Email / Home Page	www.exova.com
Authorisation	<div>Prepared By:</div> <div></div> <div>K. G. Nicholls</div> <div>Reviewed By:</div> <div></div> <div>S. Hu</div>